



3 amps through 0.1ohm shunt resistor is 0.3 watts
1/2watt minimum resistor recommended



Motor control relays and current sensors



extra pin breakout for future use

